

SAFETY DIRECTIVE

Check of throttle control guides Model G-3/600

Symbols:

Please pay attention to the following symbols throughout this document emphasizing particular information.

▲ **WARNING:** Identifies an instruction, which if not followed, may cause serious injury or even death.

■ **CAUTION:** Denotes an instruction which if not followed, may severely damage the aircraft or could lead to suspension of warranty.

◆ **NOTE:** Information for better handling.

1. General information

Issued by: Remos Aircraft GmbH Waldweg 1 D-85283 Eschelbach/Germany
Web: www.remos.com - Phone: +49-8442-967777

Release date: September-17-2005, initial issue

Date of effect: Immediately

Limit to accomplish the task: Prior to next takeoff

Issue number: SD G3-1-2005

Superseded notice: N/A

1.1 Planning information

Models affected: G-3/600

S/N affected: 163 onward

Reason: Uncorrect fitment of throttle control cable guides

Subject: Check of the throttle control cable guides

2. Material information

Tools needed: 8/10 mm open ended spanners, pliers

Parts needed: 2.8 mm shrink hose, 1.5 mm cotter pins, M6 self-locking nuts

3. Accomplishment

Level of maintenance: Heavy

Certification required: A&P Mechanic or LSA Repairman maintenance

▲ **WARNING:** Proceed this work only in a non-smoking area. Switch off ignition and secure engine against unintentional operation.


Instructions: Check location of throttle control guide as illustrated in figure 1-1 and restore to original operating configuration.

Test / Inspect: Conduct test run and rigging of throttle controls in accordance with current Maintenance Manual of the G-3/600.

Summary:

▲ **WARNING:** Non-compliance with these instructions could result in personal injury or death.

Figure 1-1



Approval of translation to best knowledge and judgement – in any case the original text in German language and the metric units are authoritative.