

Notification

ROTAX Publications

Information

Symbols:

Please pay attention to the following symbols throughout this document emphasizing particular information.

▲ WARNING: Identifies an instruction, which if not followed, may cause serious injury or even death.

CAUTION: Denotes an instruction which if not followed, may severely damage the aircraft or could lead to suspension of warranty.

NOTE: Information useful for better handling.

1. General

Issued by:	Remos Aircraft GmbH Franzfelde 31 D-17309 Pasewalk Web: www.remos.com - Telephone: +49-3973-225519-0
Release date:	January 11 th 2013
Date of effect:	January 11 th 2013
Compliance:	immediately
Release Number:	NOT-009-ROTAX-publications
Superseded notice:	none
Models affected:	G3, G3-600
Affected S/N:	up to 245
Reason:	documentation update



Notification

2. Information

- 1. Hereby REMOS Aircraft approves all publications, modifications and updates released by ROTAX.
- Hereby REMOS Aircraft decides contrary to the ROTAX Maintenance Manual that all hoses do NOT need to be replaced after 5 years. REMOS Aircraft approves that all hoses are used ON CONDITION.

REMOS wishes you safe and fun flights! Always check your aircraft before you fly!