

Notification

ROTAX Publications

Information

Symbols:

Please pay attention to the following symbols throughout this document emphasizing particular information.

- ▲ **WARNING:** Identifies an instruction, which if not followed, may cause serious injury or even death.
- **CAUTION:** Denotes an instruction which if not followed, may severely damage the aircraft or could lead to suspension of warranty.
- ◆ **NOTE:** Information useful for better handling.

1. General

<u>Issued by:</u>	Remos Aircraft GmbH Franzfelde 31 D-17309 Pasewalk Web: www.remos.com - Telephone: +49-3973-225519-0
<u>Release date:</u>	January 11 th 2013
<u>Date of effect:</u>	January 11 th 2013
<u>Compliance:</u>	immediately
<u>Release Number:</u>	NOT-009-ROTAX-publications
<u>Superseded notice:</u>	none
<u>Models affected:</u>	G3, G3-600
<u>Affected S/N:</u>	up to 245
<u>Reason:</u>	documentation update



Notification

2. Information

1. Hereby REMOS Aircraft approves all publications, modifications and updates released by ROTAX.
2. Hereby REMOS Aircraft decides contrary to the ROTAX Maintenance Manual that all hoses do **NOT** need to be replaced after 5 years. REMOS Aircraft approves that all hoses are used **ON CONDITION**.

**RE MOS wishes you safe and fun flights!
Always check your aircraft before you fly!**