

documentation update



Symbols:

Please pay attention to the following symbols throughout this document emphasizing particular information.

WARNING: Identifies an instruction, which if not followed, may cause serious injury or even

CAUTION: Denotes an instruction which if not followed, may severely damage the aircraft or could lead to suspension of warranty.

♦ NOTE: Information useful for better handling.

General

Issued by: REMOS AG Franzfelde 31 D-17309 Pasewalk

Web: www.remos.com - Telephone: +49-3973-225519-0

Release date: 30. January 2018

<u>Date of effect:</u> 30. January 2018

<u>Compliance:</u> no compliance required, but recommended on own discretion

Release Number: NOT-017-documentation-update

Superseded notice: NOT-016-documentation update

Models affected: G3, G3/600 and GX, certified as US-LSA or EASA-PtF

Affected S/N: all aircraft

Reason: documentation update



2. Pilot Operating Handbook

2.1 REMOS G3 and G3/600

No updates available.

2.2 REMOS GX

The tables below list the actual revision of the sections of the pilot operating handbook. It is not required to update the aircraft's pilot operating handbook, though it is recommended. The handbooks can either be downloaded from the website www.remos.com or be requested via service@remos.com.

EXPLORER / AVIATOR-I / AVIATOR-II / GXAVIATOR

The POH is managed under reference number 104177, released December 2017.

Section	Description	Document Number	Revision
0	Introduction	G3-8 MA FM 1200	R07
1	General Information	G3-8 MA FM 1201	R07
2	Operating Limitations	G3-8 MA FM 1202	R07
3	Emergency Procedure	G3-8 MA FM 1203	R07
4	Normal Procedures	G3-8 MA FM 1204	R07
5	Performance	G3-8 MA FM 1205	R07
6	Weight- and-Balance	G3-8 MA FM 1206	R06
7	Systems	G3-8 MA FM 1207	R06
8	Aircraft Ground Handling, Service	G3-8 MA FM 1208	R07
9	Supplement Flight Training	G3-8 MA FM 1209	R07
10	Supplement Glider Towing	G3-8 MA FM 1210	R07
11	Supplement Banner Towing	G3-8 MA FM 1211	R04
12	Supplement Cont' Airworthiness	G3-8 MA FM 1212	R03
13	Supplement Abbreviated Checklists	G3-8 MA FM 1213	R01

▲ WARNING: Compliance with notification NOT-014 is implicitly required to use the updated pilot operating handbook.

GXeLITE

This handbook has been withdrawn. No GXeLITE has been produced as LSA.



GXNXT (not for USA)

The POH is managed under reference number 104176, released December 2017.

Section	Description	Document Number	Revision
0	Introduction	G3-8 MA FM 5200	R03
1	General Information	G3-8 MA FM 5201	R01
2	Operating Limitations	G3-8 MA FM 1202	R07
3	Emergency Procedure	G3-8 MA FM 1203	R07
4	Normal Procedures	G3-8 MA FM 1204	R07
5	Performance	G3-8 MA FM 5205	R01
6	Weight- and-Balance	G3-8 MA FM 1206	R06
7	Systems	G3-8 MA FM 5207	R03
8	Aircraft Ground Handling, Service	G3-8 MA FM 1208	R07
9	Supplement Flight Training	G3-8 MA FM 1209	R07
10	Supplement Glider Towing	G3-8 MA FM 1210	R07
11	Supplement Banner Towing	G3-8 MA FM 1211	R04
12	Supplement Cont' Airworthiness	G3-8 MA FM 1212	R03
13	Supplement Abbreviated Checklists	G3-8 MA FM 1213	R01

▲ WARNING: Compliance with notification NOT-014 is implicitly required to use the updated pilot operating handbook.

GXnXES (USA only)

The POH is managed under reference number 104178, released December 2017.

Section	Description	Document Number	Revision
0	Introduction	G3-8 MA FM 6200	R03
1	General Information	G3-8 MA FM 5201	R01
2	Operating Limitations	G3-8 MA FM 1202	R07
3	Emergency Procedure	G3-8 MA FM 1203	R07
4	Normal Procedures	G3-8 MA FM 1204	R07
5	Performance	G3-8 MA FM 5205	R01
6	Weight- and-Balance	G3-8 MA FM 1206	R06
7	Systems	G3-8 MA FM 5207	R03
8	Aircraft Ground Handling, Service	G3-8 MA FM 1208	R07
9	Supplement Flight Training	G3-8 MA FM 1209	R07
10	Supplement Glider Towing	G3-8 MA FM 1210	R07
11	Supplement Banner Towing	G3-8 MA FM 1211	R04
12	Supplement Cont' Airworthiness	G3-8 MA FM 1212	R03
13	Supplement Abbreviated Checklists	G3-8 MA FM 1213	R01

▲ WARNING: Compliance with notification NOT-014 is implicitly required to use the updated pilot operating handbook.



3 Maintenance Handbook

3.1 REMOS G3 and G3/600

The handbook is not updated. REMOS hereby defines:

All applicable procedures defined in the maintenance handbook of the REMOS GX are valid for the REMOS G3 and G3/600 as well. For spare parts it is not acceptable to use GX parts, genuine G3 parts are required.

3.2 REMOS GX

No updates available. The current revision of the maintenance handbook is rev03. It is not required to update the aircraft's maintenance handbook, though it is recommended. The handbooks can be requested via service@remos.com.

4 Type Certificate Datasheet

The datasheets can be downloaded from the website www.remos.com.

4.1 REMOS G3 and G3/600

The document number of the datasheet for ASTM-LSA is G3-8 RE OA 1030, current revision is R08.

4.2 REMOS GX

The document number of the datasheet for ASTM-LSA is G3-8 RE OA 0250, current revision is R12.

The document number of the datasheet for EASA PtF is G3-8 RE OA 1060, current revision is R01.

5. Service and Maintenance Checklists

The checklist can be downloaded from the website www.remos.com.

The document number of the maintenance checklist for ASTM-LSA and EASA PtF is G3-8 RE OA 0730, current revision is R08. This is applicable for the REMOS models G3, G3/600 and GX.

6. Checklists for Annual Condition Inspection

The checklist can be downloaded from the website www.remos.com.

The document number of the checklist for the annual condition inspection for ASTM-LSA is G3-8 RE OA 0290, current revision is R06. This is applicable for the REMOS models G3, G3/600 and GX.

The document number of the checklist for the annual condition inspection for EASA PtF is G3-8 RE OA 0291, current revision is R06.

REMOS wishes you safe and fun flights! Always check your aircraft before you fly!